


Jones' Meadow  
11 as now

Main (South branch) just above  
junction with  
Pass Creek.  
Temp.  $48^{\circ}$  F. (in more sluggish channel  
draining bog primarily)

Width 5 feet

  
shoal  
above surface.

Three stakes, notch at present level.

Stone

just awash

According to log in stream water  
has recently been higher.

Placed just an inch above just 3 in.  
n. of two stakes.


Depth to next <sup>n.</sup> stake now  $2\frac{1}{2}$  in.

Another stone placed just awash in main channel

Temp in Main Channel (South)  $48^{\circ}$  F.

11:35 - Water appears to be rising slightly.

See notes & spec. n. submerged stake

Note: In all places , the bottom 7 or 8 in. - water level